



Ford Motor Company
Ford Customer Service Division
P. O. Box 1904
Dearborn, Michigan 48121-1904



39029/196483/0499



JOSEPH G KLEYNENBERG
7265 PACKER DR NE
BELMONT, MI 49306-9713

January 2016

***** IMPORTANT SAFETY RECALL *****
(PROGRAMA DE SEGURIDAD IMPORTANTE)

Safety Recall Notice 15S39 / NHTSA Recall 15V-861
Aviso de Revisión de Seguridad 15S39

2003 Crown Victoria
Your Vehicle Identification Number (VIN): 2FAHP74W13X166352

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue? On your vehicle, it is possible that the lighting control module that supplies power to the headlights may fail. This may result in the headlights not illuminating, increasing the risk of crash at night. The headlights may have intermittent operation or flicker prior to loss of headlights. In the event of the loss of headlights, the flash-to-pass operation is still functional.

What will Ford and your dealer do? Ford Motor Company is working closely with its suppliers to produce parts for this repair. When parts become available, Ford Motor Company will notify you via mail to schedule a service appointment with your dealer for repairs to be completed free of charge (parts and labor).

What should you do? When parts are available, Ford Motor Company will send a letter to inform you that parts are available and to contact your dealer to schedule a repair. Please wait to contact your dealer, unless you are currently experiencing intermittent or inoperative headlights on your vehicle.

Have you previously paid for this repair?

You may be eligible for a refund of previously paid repairs. Refunds will only be provided for service related to intermittent or inoperative headlights where the lighting control module was the cause. To verify eligibility and expedite reimbursement, give your paid original receipt to your dealer.

Refund requests may also be sent directly to Ford Motor Company. To request your refund from Ford, send the refund request with all required documentation, including your original repair receipt (no photocopies), to Ford Motor Company at P.O. Box 6251, Dearborn, Michigan 48121-6251. Refund requests mailed to this address may take up to 60 days to process. Your original receipt will be returned to you.

Detailed information regarding eligibility for Ford's reimbursement program and documentation requirements may be obtained by contacting the Ford Customer Relationship Center at 1-866-436-7332.

Thank you for your attention to this important matter.

Ford Customer Service Division